


Dovodna cev se ne isporučuje sa obrtnim priključkom



TIP	A	B	C	D	$D_1$	$L_1$	$L_2$	$L_3$	$L_4$	$L_6$	P	S
01	G 3/8" RH	G 3/8"	G 1/4"	10	45	16	26	64	124	36	M6	8
02	G 3/8" LH	G 3/8"	G 1/4"	10	45	16	26	64	124	36	M6	8
03	G 1/2" RH	G 1/2"	G 3/8"	13	57	19	35	79	147	40	G 1/8"	8
04	G 1/2" LH	G 1/2"	G 3/8"	13	57	19	35	79	147	40	G 1/8"	8
05	G 3/4" RH	G 3/4"	G 1/2"	18	73	19	34	95	171	46	G 1/4"	12
06	G 3/4" LH	G 3/4"	G 1/2"	18	73	19	34	95	171	46	G 1/4"	12
07	G 1" RH	G 1"	G 1/2"	25	83	22	42	108	200	59	G 3/8"	12
08	G 1" LH	G 1"	G 1/2"	25	83	22	42	108	200	59	G 3/8"	12
09	G 1 1/4" RH	G 1 1/4"	G 3/4"	32	91	28	54	119	234	72	G 1/2"	14
10	G 1 1/4" LH	G 1 1/4"	G 3/4"	32	91	28	54	119	234	72	G 1/2"	14
11	G 1 1/2" RH	G 1 1/2"	G 1"	38	108	29	72	149	270	76	G 3/4"	16
12	G 1 1/2" LH	G 1 1/2"	G 1"	38	108	29	72	149	270	76	G 3/4"	16
13	G 2" RH	G 2"	G 1 1/4"	48	118	29	65	165	312	96	G 1"	26
14	G 2" LH	G 2"	G 1 1/4"	48	118	29	65	165	312	96	G 1"	26