



$\varnothing d_1$	$\varnothing d_2$	$\varnothing d_3$	$\varnothing d_4$	$\varnothing d_5$	L_1	L_2	L_3	L_4
20	70	105	140	14	150	100	50	76
30	80	115	150	14	155	100	55	76
40	90	125	160	14	160	100	60	76
50	100	140	180	18	165	110	55	76
60	120	160	200	18	170	110	60	80
70	130	170	210	18	175	110	65	85
80	140	180	220	18	180	110	70	88
90	160	205	245	22	185	120	65	88
100	170	215	255	22	190	120	70	90
110	180	225	265	22	195	120	75	90