



d_3	d_1	$n \times d_2$	d_4	d_8	$\varnothing k$	L_1	L_2	L_1'	d_{10}	d_{20}	A, B	C	L_3	a_1
30,33,35,38	175	4x18	110	95	145	210	33,5	110	M12	M16	G 3/8	G 1/8	28	109,5
40	175	4x18	110	95	145	210	33,5	110	M12	M16	G 3/8	G 1/8	28	109,5
43,45,48	240	8x18	176	107	210	215	33,5	115	M12	M16	G 3/8	G 1/8	28	133
50	240	8x18	176	107	210	215	33,5	115	M12	M16	G 3/8	G 1/8	28	133
53,55,58	240	8x18	176	121	210	225	33,5	119	M12	M16	G 3/8	G 1/8	35	146
60	240	8x18	176	121	210	225	33,5	119	M12	M16	G 3/8	G 1/8	35	146
63,65,68,70,75	275	8x22	204	150	240	265	45	133	M16	M20	G 1/2	G 1/8	40	190
80	275	8x22	204	150	240	265	45	133	M16	M20	G 1/2	G 1/8	40	190
85,90,95	305	8x22	234	174	270	270	45	138	M16	M20	G 1/2	G 1/8	40	220
100	305	8x22	234	174	270	270	45	138	M16	M20	G 1/2	G 1/8	40	220
105,110,115,120	330	8x22	260	200	295	312	45	139	M20	M20	G 1/2	G 1/8	40	249
125	330	8x22	260	200	295	312	45	139	M20	M20	G 1/2	G 1/8	40	249
130,135	395	12x22	313	219	350	318	52	153	M20	M20	G 1/2	G 1/8	22	264
140	395	12x22	313	219	350	318	52	153	M20	M20	G 1/2	G 1/8	22	264
145,150,155	395	12x22	313	219	350	318	52	161	M20	M20	G 1/2	G 1/8	44	304
160	395	12x22	313	238	350	345	52	161	M20	M20	G 1/2	G 1/8	44	304