



$\varnothing d_1$	$\varnothing d_2$	$\varnothing d_3$	$\varnothing d_4$	$\varnothing d_5$	L_1	L_2	L_3	L_4
20	70	105	-	-	-	-	-	-
30	80	115	74	138	151	98	53	75
40	90	125	84	148	157,5	98,5	59	76
50	100	140	94	168	161	108	53	85,5
60	120	160	114	188	164	107	57	86
70	130	170	124	198	168	106	62	79,5
80	140	180	131	208	174	107	67	82,5
90	160	205	153	248	182	119	63	93,5
100	170	215	158	258	200	132	68	98,6
110	180	225	174	268	203	130	73	98